

Project No.	Client	Location	Boring No.	Monitoring Well No.	Date
01105	Metro Car Wash	2950 Harbor, CM	CB-4	N/A	August 9, 2005
PID	BLOWS/ft. Sampler	DEPTH in feet	USCS Designation & Soil Type	Color	Secondary Characteristics
0	9-11-15	5	CL-Silty Clay	Dark Brown	Stiff, SI Damp, No Odor
0	12-14-18	10		Medium Brown	Dry
0	9-11-15	15		Tan	
0	8-12-15	20		Tan to Grey	
0	10-13-14	25		Olive Grey	
0	9-9-11	30		Reddish Brown	
0	7-10-16	35		Light Grey	
10	9-12-17	40		Tan	Very Slight Odor
0	16-18-21	45	SM-Silty Sand	Grey to Tan	Very Dense, Moist, No Odor
0	8-11-19	50			Damp
0	10-13-15	55		Greyish Green	
0	17-19-22	60			
0	19-21-23	65			
0	17-19-22	70		Tan	Wet
0	20-24-29	75	SP-Poorly Graded Sands		
Field Engineer	Drilling Contractor	Drilling Foreman	Boring terminated at 75 feet below grade. Groundwater at 67'. Boring backfilled with soil of origin and capped with bentonite plug (2'). Resurfaced with concrete		
M. Anselmo	J & H	Conrad			